



# Falla en transformador seco

Name:IMAGE018.IMG



Visible Image





**Delta-Two Data**

Num	P-A	P-B	Delta	Ratio(%)
1	69.2	108.3	39.1	54.3

### Conclusion and Advice

**1 Findings :**

EXTRUSION, TRANSFORMADOR TR-16, FASE TAPE ROJO

**2 Potential danger :**

HOT SPOT EN CONEXION . LIMPIAR Y REAPRETAR

**3 Solution proposal :**

DESARMAR, LIMPIAR Y REAPRETAR CONEXION.

**4 Comments :**

PRIORIDAD IMPORTANTE