




Infratherm Termografia			Inspected Location:		
Inspected By: Fernando Castillo			Termógrafo Nivel II por ASNT		
File Name	IRI_20190515_010854.jpg	Created Date	2019/05/15	Created Time	08:08:54
Emissivity	0.95	Humidity	70%	Distance	3.0mm
Ambient	28.5°C	Max Temp	159.9°C	Min Temp	150° C
IR Image				C1MaxT	151.6°C
				C1MinT	--°C
Visible Image				C1AvgT	--°C
				C1Emissivity	0.95
				C1Distance	3.0m
				C1Humidity	70%
				R1MaxT	159.9°C
				R1MinT	--°C
				R1AvgT	--°C
				R1Emissivity	0.95
				R1Distance	3.0m
				R1Humidity	70%
Component Detail				 0.wav	
Analysis & Recommended Action:					